



A Textron Company

Authorized Customer Service Facility

Arrow Aviation Co. LLC Broussard, Louisiana

*Has satisfactorily met all specified requirements to qualify as a
Bell-Approved Independent Customer Service Facility
for the following Bell helicopters.*

Listed Products

Field Maintenance: 205/206A,B/206L/212/214ST/222/230/407/412/430/UH-1H
Component Overhaul: 206A,B/206L/212/222/230/407/412/430/UH-1H
Structural Repair - Cabin: 205/206A,B/206L/212/214B/214ST/407/412/UH-1H
Structural Repair - Tailboom: 205/206A,B/206L/212/214B/214ST/407/412/UH-1H
Rotor Blade Repair:

Shane Eddy
Vice President, Customer Support and Services



Effective: 01 January 2008

Expires: 31 December 2011